


## BUILDING SAFETY CERTIFICATE

Certificate that the existing building of SRI MAHADASHWARA TRUST at nidaghatta village kasaba hobli ,malavalli taluk,comprised G+5 floors occupied by CRYSTAL INTERNATIONAL SCHOOL complied with the building safety requirements in accordance with National building code rules and verified by the officers Asst. Exucutive Engineer ,PWD malavalli on 29/04/2026 in the presence of Sri Siddaraju Chairman CRYSTAL INTERNATIONAL SCHOOL and the building is fit for occupied upto Secondary classes in accordance with rules and subject to compliance of this specific condition to appended:

  
12/05/2026

Executive Engineer  
PWD Division, Mandya.

  
PRINCIPAL  
Crystal International School  
Kanakapura Main Road  
Malavalli - 571430

For SRI MAHADESHWARA EDUCATION TRUST

  
Chairman

ಕರ್ನಾಟಕ ಸರ್ಕಾರ



(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ಸರ್ಕಾರಿ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಾರ್ಯಾಲಯ ನಂ.3, ಉಪ-ವಿಭಾಗ, ಮಳವಳ್ಳಿ

ಸಂಖ್ಯೆ ಸಕಾಇ-3/ಲೋ.ಇ/ಮಳವಳ್ಳಿ /ಸ.ಇಂ-01/ದೃಢೀಕರಣ ಪತ್ರ/2026-27/112

ದಿನಾಂಕ: 05-05-2026

ಇವರಿಗೆ,

ಅಧ್ಯಕ್ಷರು,

ಶ್ರೀ ಮಹದೇಶ್ವರ ಎಜುಕೇಷನ್ ಟ್ರಸ್ಟ್,  
ನಂ.264/6 ನಿಡಘಟ್ಟ, ಕನಕಪುರ ಮುಖ್ಯ ರಸ್ತೆ,  
ಮಳವಳ್ಳಿ-571430.

ಮಾನ್ಯರೆ,

**ವಿಷಯ :-** ಶ್ರೀ ಮಹದೇಶ್ವರ ಎಜುಕೇಷನ್ ಟ್ರಸ್ಟ್‌ನ ಶಾಲಾ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.

**ಉಲ್ಲೇಖ:-** 1. ತಮ್ಮ ಕಛೇರಿ ಪತ್ರ, ದಿನಾಂಕ: 23-04-2026.

2.ಕರ್ನಾಟಕ ಸರ್ಕಾರ ಅಪರ ಕಾರ್ಯದರ್ಶಿ, ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ ರವರ ಸುತ್ತೋಲೆ ಪತ್ರ ಸಂಖ್ಯೆ: ಲೋಇ 59 ಬಿಇಡಿ 2019 ಬೆಂಗಳೂರು ದಿ:06.05.2022.

\*\*\*

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖಿತ ಪತ್ರದಲ್ಲಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ದೃಢೀಕರಣ ಪತ್ರವನ್ನು ನೀಡಲು ಕೋರಿರುತ್ತೀರಿ. ಅದರಂತೆ ದಿನಾಂಕ: 29.04.2026 ರಂದು ಸಂಬಂಧಪಟ್ಟ ಇಂಜಿನಿಯರ್ ಹಾಗೂ ಅಧ್ಯಕ್ಷರು, ಶ್ರೀ ಮಹದೇಶ್ವರ ಎಜುಕೇಷನ್ ಟ್ರಸ್ಟ್ ರವರೊಂದಿಗೆ ಸದರಿ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ಪರಿವೀಕ್ಷಣೆ ಕೈಗೊಳ್ಳಲಾಯಿತು.

ಶ್ರೀ ಮಹದೇಶ್ವರ ಎಜುಕೇಷನ್ ಟ್ರಸ್ಟ್ ಮಳವಳ್ಳಿ ತಾಲ್ಲೂಕು, ಮಂಡ್ಯ ಜಿಲ್ಲೆ, ಇಲ್ಲಿನ ಶಾಲಾ ಕಟ್ಟಡವನ್ನು Plinth Area 763.68 ಚ.ಮೀ ಜಾಗದಲ್ಲಿ 2023 ರಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿದ್ದು, ನೆಲ ಮಹಡಿಯೊಂದಿಗೆ ಐದು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವು ಆರ್.ಸಿ.ಸಿ ಮೇಲ್ಭಾಗವೇಯಿಂದ ಕೂಡಿದ್ದು, ಕಟ್ಟಡವು ಗ್ರಾನೈಟ್ ನೆಲಹಾಸು, ಕಬ್ಬಿಣದ ಕಿಟಕಿಗಳು ಮತ್ತು ಕಬ್ಬಿಣದ ಗ್ರಿಲ್ ಗಳಿಂದ ಕಟ್ಟಡವು ನಿರ್ಮಾಣಗೊಂಡಿರುತ್ತದೆ. ಮುಂದುವರೆದು ಹಾಜರಿದ್ದ ಶಾಲಾ ಅಧ್ಯಕ್ಷರೊಂದಿಗೆ ಒಳಭಾಗ ಹಾಗೂ ಹೊರಭಾಗವನ್ನು ಪರಿವೀಕ್ಷಣೆ ಮಾಡಲಾಗಿ, ಸದರಿ ಕಟ್ಟಡವು ನೆಲ ಮಹಡಿಯೊಂದಿಗೆ ಐದು ಅಂತಸ್ತಿನ ಕಟ್ಟಡವಾಗಿದ್ದು, ನೆಲ ಮಹಡಿಯಲ್ಲಿ ಆರುತರಗತಿ ಕೊಠಡಿಗಳು, 03 ಬಾಲಕರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, 03 ಬಾಲಕಿಯರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, ಒಂದು ಸ್ಟಾಫ್ ಟಾಯ್ಲೆಟ್ ರೂಮ್, ಒಂದು ಫೈರ್ ಕಂಟ್ರೋಲ್ ರೂಮ್, 02 ಲಿಫ್ಟ್ ಮತ್ತು 02 ಸ್ಟೇರ್ ಕೇಸ್‌ಗಳು, ಮೊದಲನೇ ಮಹಡಿಯಲ್ಲಿ ಆರುತರಗತಿ ಕೊಠಡಿಗಳು, 03 ಬಾಲಕರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, 03 ಕೇಸ್‌ಗಳು, ಮೊದಲನೇ ಮಹಡಿಯಲ್ಲಿ ಆರುತರಗತಿ ಕೊಠಡಿಗಳು, 03 ಬಾಲಕರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, 03 ಬಾಲಕಿಯರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, ಒಂದು ಸ್ಟಾಫ್ ಟಾಯ್ಲೆಟ್ ರೂಮ್, ಒಂದು ಫೈರ್ ಕಂಟ್ರೋಲ್ ರೂಮ್, 02 ಲಿಫ್ಟ್ ಮತ್ತು 02 ಸ್ಟೇರ್ ಕೇಸ್‌ಗಳು, ಎರಡನೇ ಮಹಡಿಯಲ್ಲಿ ಆರುತರಗತಿ ಕೊಠಡಿಗಳು, 03 ಬಾಲಕರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, 03 ಬಾಲಕಿಯರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, ಒಂದು ಸ್ಟಾಫ್ ಟಾಯ್ಲೆಟ್ ರೂಮ್, ಒಂದು ಫೈರ್ ಕಂಟ್ರೋಲ್ ರೂಮ್, 02 ಲಿಫ್ಟ್ ಮತ್ತು 02 ಸ್ಟೇರ್ ಕೇಸ್‌ಗಳು ಮತ್ತು 02 ಸ್ಟಾಫ್ ರೂಮ್ ಗಳು, ಮೂರನೇ ಮಹಡಿ, ನಾಲ್ಕನೇ ಮಹಡಿ ಮತ್ತು ಐದನೇ ಮಹಡಿಯಲ್ಲಿ ಪ್ರತಿ ಮಹಡಿಯಲ್ಲಿಯೂ ಆರುತರಗತಿ ಕೊಠಡಿಗಳು, 03 ಬಾಲಕರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, 03 ಬಾಲಕಿಯರ ಟಾಯ್ಲೆಟ್ ರೂಮ್‌ಗಳು, ಒಂದು ಸ್ಟಾಫ್ ಟಾಯ್ಲೆಟ್ ರೂಮ್, ಒಂದು ಫೈರ್ ಕಂಟ್ರೋಲ್ ರೂಮ್, 02 ಲಿಫ್ಟ್, 02 ಸ್ಟೇರ್ ಕೇಸ್‌ಗಳು ಮತ್ತು ಒಂದು ಭೌತಶಾಸ್ತ್ರ ಲ್ಯಾಬ್ ಇರುವುದು ಕಂಡುಬಂದಿರುತ್ತದೆ.



Government of Karnataka

(Public Works Department)

Office of the Assistant Executive Engineer, PWD No.3, Sub-Division, Malavalli

No: 2025-26-112

Date: 05-05-2026

To,

The President,

Sri Mahadeshwara Education Trust,

No. 264/6 Nidaghatta, Kanakapura Main Road,

Malavalli - 571430.

Sir,

Subject: Regarding issuance of a Safety Certificate for the school building of Sri Mahadeshwara Education Trust.

\*Reference\*:

1. Your office letter dated: 23-04-2026.

2. Circular No: LO.I 59 BIDIDI 2019, Bangalore, dated: 06.05.2022, of the Under Secretary to Government of Karnataka, Public Works Department.

With reference to the above subject, you have requested to inspect the school building and issue a Building Safety Certificate. Accordingly, on 29.04.2026, the concerned Engineer along with the President, Sri Mahadeshwara Education Trust, inspected the said school building.

The school building of Sri Mahadeshwara Education Trust, Malavalli Taluk, Mandya District, was constructed in 2023 on a plinth area of 763.68 sq.m. It is a 5-storeyed building with an R.C.C. roof. The building has granite flooring, glass windows, and glass grills. During inspection along with the present school president, the building was found to be 5-storeyed with the following details:


\*Ground Floor\*: 6 classrooms, 03 boys' toilet rooms, 03 girls' toilet rooms, 01 staff toilet room, 01 fire control room, 02 lifts and 02 staircases.

\*First Floor\*: 6 classrooms, 03 boys' toilet rooms, 03 girls' toilet rooms, 01 staff toilet room, 01 fire control room, 02 lifts, 02 staircases.

\*Second Floor\*: 6 classrooms, 03 boys' toilet rooms, 03 girls' toilet rooms, 01 staff toilet room, 01 fire control room, 02 lifts, 02 staircases and 02 staff rooms.

\*Third, Fourth and Fifth Floors\*: 6 classrooms each, 03 boys' toilet rooms each, 03 girls' toilet rooms each, 01 staff toilet room each, 01 fire control room each, 02 lifts, 02 staircases and 01 Physics lab.

The said school building is 03 years old from the date of construction. As there were no test reports available for the materials used in the construction of the building such as concrete, steel, cement, wood, etc., as suggested in reference (2) of the Government Circular, two types of Non-Destructive Tests were conducted.

  
**K. DWARAKANATH**  
B.Sc., LL.B.  
Advocate & Notary,  
MALAVALLI.



The test reports for the said building were obtained by conducting Non-Destructive Tests, namely Rebound Hammer Test/Ultrasonic Pulse Velocity test, by Prof. Dr. N. Jayaramappa, working in the Department of Civil Engineering, UVCE, Jnana Bharathi Campus, Bangalore University, Bangalore 560056. In the said report, suggestions have been given to rectify the dampness and cracks observed in the walls of the building, and it is recommended to implement them immediately.


The following documents are submitted herewith:

1. As per Built Drawing
2. Ultrasonic Pulse Velocity Test Report
3. Rebound Hammer Test Result.

As suggested in serial number (2) of the Government Circular mentioned in reference (2), to pay a fee of Rs. 1000.00 for one school/college in a rural area, the said institution has paid Rs. 1000.00 to the challan reference no: CR0526005900033476.

All the main parts of the said school building were inspected. At this time, the upper floors of the building are opined to be safe. It is suggested to adopt the floor plan and implement the quick construction results on each floor of the said building. It is suggested to immediately implement the recommendations given regarding the maintenance of the said building, and the responsibility for maintaining the said building lies with the said institution.

The Safety Certificate for the school building is issued for a period of five years, subject to the conditions mentioned below. If any changes or construction work are carried out on the building in the future, this certificate will stand automatically cancelled. Therefore, this certificate is issued for the building of Sri Mahadeshwara Education Trust, No. 264/6 Nidaghatta, Kanakapura Main Road, Malavalli, for educational purposes only. Further, the Safety Certificate for the said school building has been issued and this certificate is liable to be withdrawn at any time.

*Witnessed by me*  


**K. DWARAKANATH**  
B.Sc., LL.B.  
Advocate & Notary  
MALAVALLI.

Assistant Executive Engineer  
No.3, Public Works Department, Sub-Division  
Malavalli.